



TTX660
6-CHANNEL 2.4GHz SPREAD SPECTRUM RADIO SYSTEM

TECHNICAL NOTICE

Some Tactic TTX660 computer transmitters have a programming error which causes the assigned switch for CH5 and CH6 to be non-functional after the transmitter power has been cycled (firmware versions **prior** to: ver 2.005). The switch function can be restored by re-assigning the switch in the CH5 and CH6 set menu option. This error does not affect any other function in the transmitter. If your TTX660 does not exhibit this problem or this error would not affect your use of the TTX660, then no action needs to be taken by you. If your radio exhibits this error and you would like the issue corrected, then you will need to ship your TTX660 to Hobby Services for a firmware update.

The transmitter can be shipped in the original packaging or a sturdy box with adequate padding to ensure the transmitter will not become damaged during shipping. Please include

documentation with the transmitter stating the problem (the reason you have sent the transmitter to the service center) and the request for the firmware update. When received, the transmitter will be promptly serviced and returned to you. The firmware update and return shipping is a no-cost service so no payment needs to be included.

*For the firmware update, **Hobby Services**
please ship your 3002 N. Apollo Drive, Suite #1
TTX660 transmitter to: Champaign, IL 61822*

NOTE: This firmware update is only for the TTX660 transmitter. The update does not add any additional features to the transmitter or change any other existing functions. This update is only for the purpose of correcting the switch assignment error for CH5 and CH6.