


If the optional AnyLink cable TACM0003 will not power AnyLink with your Futaba® transmitter, it's most likely due to an improperly extended negative spring terminal in the transmitter's trainer port.



To correct this problem, please send the Futaba transmitter to the Futaba Service Center along with a proof of purchase for TACM0003. The spring will be repaired and verified to work with AnyLink at no charge. In addition, the transmitter will be returned to you postage paid.

Futaba Service Center 3002 N Apollo Dr. Suite #1 Champaign, II 61822