TECHNICAL NOTICE



Please note there is an error on the original Exploded View for the Heli-Max AXE CP. The orientation of the main rotor grip shown on the original exploded view is incorrect. Please use this drawing when working on, repairing or reassembling the main rotor head. We apologize for any inconvenience this may have caused.

HMXE04**ADDN02