


tidewater

Addendum



On page 6, **Setting Up the Radio System**, is an image of how the servo reversing switches on the radio should be positioned. On some models this could be incorrect.

Please double check the movement of the control surfaces with the movement of radio control sticks and be sure they move as shown in the diagram on page 8, **Check the Controls**.

