



For modelers using Futaba brand high-torque servos.

To get the most enjoyment and performance from the R7018SB and your aircraft, we suggest that you operate no more than six high-torque servos at the same time.

Using more than six high-torque servos—such as the BLS172SV, BLS177SV or S9177SV—could cause the R7018SB to overheat and damage its circuitry. Damaged circuitry could, in turn, lead to a loss of performance or other difficulties.

This may also be true with other brands of high-torque servos.