
SIREN EP HOTLINER

TECHNICAL NOTICE



If the spinner interferes with the fuselage/cowl, you may need to sand the rear edge of the spinner to make it fit. It may be necessary to remove some material from the rear edge of the spinner before it fits without contacting the fuselage. The spinner is correctly mounted when the "shoulder" of each cutout rests on the prop hub AND the rear edge does not contact the fuselage at any point when the propeller is rotated.