


The first picture of step 9 on page 16 is incorrectly labeled. The distance from the firewall to the drive washer should be measured as follows:



Copyright © 2009 GPMA1328TECH01