

RimFire 28mm Brushless Motor Technical Notice



The two prop saver 2.5 x 6mm machine screws should be adequately tightened using threadlocking compound prior to installing the motor into its application. The screws must be tightened with threadlocking compound even if a propeller is installed using a collet adapter on the opposite end of the motor. If the screws are not tight against the motor shaft, the shaft could come loose from the motor case.