



ELDER .40

PRODUCT IMPROVEMENT SUPPLEMENT

Page 20, Step 35: The plans and manual show the wing bolt mounting plate in the wrong location. The mounting plate should be installed 5/8" lower in the fuselage than shown. After the mounting plate has been glued in place, use some leftover 1/4" x 1/4" basswood to reinforce it, as shown in the photograph and plan correction.

