## HOBBICO STAR PLUG TECH NOTICE

The Star Plug on the battery may have some excess material on the terminals inside the connector. Even when fully connected, this could prevent the plug from making connection with the ESC.

The excess material can be removed with a #11 hobby blade.

**IMPORTANT!** While removing the excess material be careful not to short circuit the battery.

