



This kit has been updated for independent aileron servo installation only.

A total of 5 servos are required for kit completion.

© 2013 Hobbico,® Inc. PMMA0125 Tech01