


When test-fitting the stab/fin assembly to the fuselage as shown in step 2, check to see if there is a gap between the rudder and the fuselage. If a gap does not exist, proceed with assembly as instructed in the manual. If there is a gap, trim the top of the fuselage as described below.



Use a straightedge and a sharp hobby knife to trim end of the fuselage top as necessary to close the gap—typically removing 1/16" to 3/32" [1.6–2.4mm] is suitable. This will bring the stab/fin assembly forward, eliminating the gap.

Copyright © 2009 GPMA1133Tech01